



40 Series CD Player Release Notes

Release v1.0.151

Versions

Bootloader	v1.8.0
CD	v1.0.151
CD-Servo	v1.2.0
Fonts	v1.0.1
Images	v1.0.40
Languages	v1.0.1
PSU	v1.0.10

Changes

1. Bootloader v1.8

Release v1.0.149

Versions

Not Available

Changes

1. REDMINE 986 - Plug in network while in setup menu, display clash and remote unresponsive
- Partial fix
2. REDMINE 1053 - Add servo version in settings > about
3. REDMINE 1057 - USB Upgrade download fails when reading from USB drive

Release v1.0.141

Versions

Not Available

Changes

1. REDMINE 826 - Power up with disc
2. REDMINE 993 - When update OK or Back - make keys responded to only OK and BACK
3. REDMINE 1034 - Standby timer appears to activate if disc is playing
4. REDMINE 1046 - New unit attempts upgrade to new version when first connected to network
5. REDMINE 1051 - Calibration error messages disk should be disc
6. REDMINE 1052 - Cannot roll back software over USB - CD tested
7. 2 column items menu handling
8. v1.7 Bootloader

Release v1.0.128

Versions

Bootloader	v1.5.0
CD	v1.0.128
CD-Servo	v1.2.0
Fonts	v1.0.1
Images	v1.0.40
Languages	v1.0.1
PSU	v1.0.9

Changes

1. CD Servo v1.2