



40 Series Integrated Amplifier Release Notes

Release v1.0.114

Versions

Amp	v1.0.114
Bootloader	v1.8.0
Fonts	v1.0.1
Images	v1.0.17
Languages	v1.0.1
PSU	v1.0.10

Changes

1. REDMINE 1009 - Encoder ring brightness
2. REDMINE 1028 - Add headphone indication when headphones plugged in to AMP
3. REDMINE 1032 - Check ARC Operation
4. REDMINE 1035 - AMP sometimes stalls at startup with splash screen and pulsing LEDs - suppression of tasks during powerup
5. REDMINE 1042 - Add fixed naming list for inputs
6. REDMINE 1057 - USB Upgrade download fails when reading from USB drive
7. REDMINE 1073 - DAC Filter, saving selection
8. REDMINE 1079 - Menu highlight bar offset over text