



40 Series Integrated Amplifier Release Notes

Release v1.0.116

Versions

Amp	v1.0.116
Bootloader	v1.9.0
Fonts	v1.0.1
Images	v1.0.17
Languages	v1.0.1
PSU	v1.0.11

Changes

1. REDMINE-803 - Display is blank, flashes lines on power up
2. REDMINE-1093 - Auto Display Off
3. REDMINE-1099 - If buttons are pressed on the unit and autohide is enabled but not triggered, key behaviour is not correct
4. REDMINE-1103 - Change Activity Sensor Active timer to 200ms

Release v1.0.115

Versions

Amp	v1.0.115
Bootloader	v1.9.0
Fonts	v1.0.1
Images	v1.0.17
Languages	v1.0.1
PSU	v1.0.11

Changes

1. REDMINE 1099 - If buttons are pressed on the unit and autohide is enabled but not triggered, key behaviour is not correct

Release v1.0.114

Versions

Amp	v1.0.114
Bootloader	v1.8.0
Fonts	v1.0.1
Images	v1.0.17
Languages	v1.0.1
PSU	v1.0.10

Changes

1. REDMINE 1009 - Encoder ring brightness
2. REDMINE 1028 - Add headphone indication when headphones plugged in to AMP
3. REDMINE 1032 - Check ARC Operation
4. REDMINE 1035 - AMP sometimes stalls at startup with splash screen and pulsing LEDs - suppression of tasks during powerup
5. REDMINE 1042 - Add fixed naming list for inputs
6. REDMINE 1057 - USB Upgrade download fails when reading from USB drive
7. REDMINE 1073 - DAC Filter, saving selection
8. REDMINE 1079 - Menu highlight bar offset over text