



40 Series CD Player Release Notes

Release 1.0.221

Versions

Bootloader	v1.19.0
CD-Servo	v1.3.0
CD	v1.0.221
Fonts	v1.0.11
Images	v1.0.40
Languages	v1.0.23
TtfFontsCN	v1.0.13
TtfFontsEU	v1.0.9
TtfFontsGL	v1.0.2
PSU	v1.0.11

Changes

1. REDMINE 1140 - Improved cap touch handling
2. REDMINE 1157 - add support for larger sized EEPROM on front panel
3. Added CN region language support
4. Added CN region update support
5. Added language support for 3.5" display
6. Aligned 3.5" display product bootloader with 5" display products
7. Bootloader improved USB stick support for upgrades
8. Bootloader update for CN region
9. Bootloader update for language support
10. Improved USB stick support for upgrades
11. Increased memory size for LVGL9 on 3.5" display
12. Optimised language text
13. Optimised position of track/time display
14. Optimised track/time display when exiting setup menu
15. Optimised upgrade text message content
16. Update bootloader to v1.19 for new product support
17. Update font files for LVGL9/EEPROM

18. Upgrade LVGL driver to latest (v9)